



Service Bulletin

Issued by Canon Europa N.V.

Copier B/W

Hardware

Model:

iR5570

iR6570

Ref No.:

iR6570-007

(F1-T01-0M5-10024-01)

Date:

September, 2005

Location:

Service Manual

Subject:

Service Manual (error code E001/ E004)

Reason:

The Remedy of E001 detail code 03 is changed. E001 detail code 0010 is added. The change and the addition are described below in blue.

T-1

Code	Description	Remedy
E001	There is an abnormal rise in temperature. After correcting the fault, be sure to reset the error.	
0003	The reading is not 150 deg C or higher or 210 deg C or lower within 30 sec.	-Check the connecting of the main/ sub/ shutter thermistors. -Check the mounting of the main/ sub/ shutter thermistors. -Exchange the main/ sub/ shutter thermistors. -Exchange the DC controller PCB.
E004	The IH power supply is faulty/ the IH control mechanism is faulty.	
0010	The power has been turned off and then on without resetting the error.	-Reset the error (COPIER>FUNCTION>CLEAR>ERR)