

SB Number:	SB 2FP-007	Creation Date: 05/09/2005
Subject:	Firmware update	
Model:	FS-3820N/3830N	

Please be informed that the firmware for FS-3820N/3830N has been changed as follows.

- Version 158.04**

	Contents	Remarks
1	When a 2 page PCL document is printed, printer will output a 1 page document with overlap.	The phenomenon has been corrected in the F/W
2	Incorrect character position when printing character string rotated by 180 and 270 degrees.	The phenomenon has been corrected in the F/W
3	High code characters are ignored when processing an operation for Esc sequence 1Bxx (xx being high code)	The phenomenon has been corrected in the F/W

	ROM Ver.	Check Sum	Label Name	U-No	Rom Type
System	158.04	B8D0H	SB21K15804	YS01	4MB-DIMM

- Version 158.05**

	Contents	Remarks
1	Certain characters are replaced by incorrect characters.	The phenomenon has been corrected in the F/W
2	After firmware upgrade the IP address is reset to factory settings.	The phenomenon has been corrected in the F/W
3	F030 error message will display when printing documents with downloaded fonts.	The phenomenon has been corrected in the F/W

	ROM Ver.	Check Sum	Label Name	U-No	Rom Type
System	158.05	3F75H	SB21K15805	YS01	4MB-DIMM

Affected Machine Serial Numbers:

Version 158.04

FS-3820N: ALD4819964 and higher
FS-3830N: ALC4719718 and higher

Version 158.05

FS-3820N: ALD4928417 and higher
FS-3830N: ALC4719718 and higher