

<b>SB Number:</b>	<b>SB 2DC-009</b>	<b>Creation Date:</b> 21/10/2004
<b>Subject:</b>	Change of feed roller to improve paper feeding	
<b>Model:</b>	<b>KM-1500</b>	

## Phenomenon

Paper is not fed from cassette and jam may occur.

## Cause

An excessive amount of paper dust attaches to the surface of the paper feed roller, resulting into 'no paper feeding' and/or jam at the regist. roller section. This phenomenon may occur especially when using other paper than recommended by Kyocera Mita.

## Countermeasure

If phenomena should occur, please replace current roller with improved roller which will improve the paper feed performance.



## Parts Table

No	Part No. OLD	Part No. NEW	Old Description	Q'ty old-new		Interchange ability	
1	2DC06030	2A806010 (or /AVR0025 / 5AAVROLL++044)	ROLLER FEED ASSY	1	1	O	O

### Affected Machine Serial Numbers:

**KM-1500:** June, 2004 production and later

### Note:

Please be informed that in addition to the above affected machine indication, all machines shipped out to KMIS territory as of 1<sup>st</sup> of July 2004 already include the new roller.