

TECHNICAL BULLETIN

TB No.: **2AV-003**

Date: 13 / 03 / 2001

MODEL: KM-1530, KM-2030


SUBJECT: Contact of 'PULLEY, BYPASS' to 'COVER, BYPASS' (unusual noise)

Phenomenon & Cause

An unusual noise is caused because the 'PULLEY, BYPASS' is in contact with the 'COVER, BYPASS'. This malfunction seems to occur just after arrival of the machine.


Temporary countermeasure

A Mylar film ($t = 0.5$) has been attached to the screw in the frame of the 'COVER, BYPASS' to separate the 'COVER, BYPASS' from the 'PULLEY, BYPASS'.



Permanent countermeasure

The shape of the 'COVER, BYPASS' has been changed so that it does not come in contact with the 'PULLEY, BYPASS'. (The temporary mylar film mentioned above is with the permanent measure discontinued.)



Note: It is not necessary to peel off the Mylar film if for some reason a 'COVER, BYPASS' needs to be replaced by a new one.

Item No.	Parts No. OLD	Parts No. NEW	Description	Q'ty old-new	Interchangeability
1	2AV06170	2AV06171	COVER, BYPASS	1 / 1	O / O

Affected Machine Serial Numbers:

Temporary countermeasure

- **KM-1530:** 37002534 and later
- **KM-2030:** 37003562 and later

Affected Machine Serial Numbers:

Permanent countermeasure

- **KM-1530 / 2030:**
Production of January, 2001 and later