

SB Number:	SB 2H0-013	Creation Date: 05/11/2008
Subject:	<i>Firmware upgrade (JS-670 detection failure and panel lock after recovering from sleep mode)</i>	
Model:	KM-2540/3040/2560/3060	

Contents of changes	Item	Contents
	JS-670 detection failure	The JS-670 may not be detected after the machine recovers from sleep mode, under the condition that the PF-670 is not connected and the drum heater is set to "ON".
	Panel lock after copying	A panel lock may occur after copying with the platen cover open, when the start key is pressed before the lamp returns to the home position.

Latest firm-ware as of July 2008 for KM-2560/3060	Type	Program No.	Check SUM	Version
	MAIN	2H0_2F00.011.006	-----	011.006
	ENGINE	2H0_1000.010.004	-----	010.004
	MMI2	2H0_7A00.011.006	-----	011.006
Latest firm-ware as of 2008 for KM-2540/3040	MAIN	2JB_2000004001	-----	004.001
	ENGINE	2JB_1000008004	-----	007.002
	LANGUAGE E	2JB_81XE001003	-----	001.003
	PRINTER FS	2JC_3F00.003.003	-----	003.003

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When above mentioned phenomena occur, please upgrade the firmware to the latest version.			

Affected serial numbers	Type	Serial number
	KM-2540/3040/2560/3060	July 2008 production