

<b>SB Number:</b>	<b>SB 2H0-002</b>	<b>Creation Date: 12/06/2008</b>
<b>Subject:</b>	<b>Firmware upgrade (Main, engine)</b>	
<b>Model:</b>	<b>KM-2560/3060</b>	

<b>Contents of changes</b>	<ol style="list-style-type: none"> <li>1. Error message "Wait for a while" when going into auto sleep mode</li> <li>2. Error code CF26F may occur after a paper jam</li> <li>3. Added automatic activation every 2 minutes</li> <li>4. Command Centre changes</li> <li>5. Change option name printed on the status page</li> <li>6. Error code C0630 may occur after MIP_PG output</li> <li>7. Error code CF445 may occur while recovering from auto sleep mode</li> <li>8. Machine does not go into auto sleep mode</li> <li>9. Error code CF603, panel lock, if the energy key is pressed continuously</li> <li>10. Panel lock while receiving a single print job of over 1200 pages</li> <li>11. Changed printing area values printed on the service status page</li> <li>12. No fax reception possible, fax transmission job keeps on processing</li> <li>13. The SIOP 0 command has been deleted</li> <li>14. Prevention of panel lock after recovering from auto sleep mode</li> <li>15. Preventing key presses of executing when the panel is set to panel lock</li> <li>16. When feeding from the bypass the leading edge may be faint</li> </ol>
----------------------------	---

<b>Latest firm-ware as of December 2007</b>	<b>Type</b>	<b>Program No.</b>	<b>Check SUM</b>	<b>Version</b>
	MAIN	2H0_2F00.004.005	-----	004.005
	MMI	2H0_7000.004.006	-----	004.006
	ENGINE	2H0_1000.006.001	-----	006.001

<b>Classification</b>	<input type="checkbox"/> Entire stock rework <input type="checkbox"/> In-field modification at next visit <input type="checkbox"/> In-field modification by case <input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomena occur, upgrade the firmware whenever necessary. Upgrade all the firmware to the latest version at the same time. Please instruct users not to turn off the power during data writing or processing to the harddisk.

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	KM-3050/4050/5050	From the production of November 2007

<b>Contents of changes</b>	<b>Item</b>	<b>Contents</b>
	1	Error message "Wait for a while" when going into auto sleep mode Pressing the start key while the machine shifts into auto sleep mode, could result in an error message (Wait for a while).
	2	Error code CF26F may occur after a paper jam Error code CF26F may occur after a paper jam
	3	Added automatic activation every 2 minutes An automatic driving function has been added to let the machine become active every 2 minutes. This is to make sure that the data flow is not interrupted.
	4	Command Centre changes The language option has been changed in the command center.

5	Change option name printed on the status page	Old Security Kit, New Data Security Kit (C) In order to acquire ISO15408, it is necessary to print the correct option name.
6	Error code C0630 may occur after MIP_PG output	After using MIP_PG output (U089), error C0630 might occur (DMA abnormal).
7	Error code CF445 may occur while recovering from auto sleep mode	When the drum Heater is on, and the start key is pressed while the machine shifts into its auto sleep mode error CF445 may occur.
8	Machine does not go into auto sleep mode	A problem could occur when using the document processor while the machine is in sleep mode. After trying to use the DP a reset was necessary, this could cause the machine not to shift into auto sleep mode.
9	Error code CF603, panel lock, if the energy key is pressed continuously	When importing the address book data with the KM-NET viewer and the power save key is continuously pressed, a lock error (CF630) may occur.
10	Panel lock while receiving a single print job of over 1200 pages	Continuously outputting a print job of 1200 pages (1 print job) causes the machine to become slower and finally show CF000 errors.
11	Changed printing area values printed on the service status page	A correction has been made in the Service status page where there was an incorrect indication of printing area values.
12	No fax reception possible, fax transmission job keeps on processing	Using the fax function could result in a 10 millisecond delay, when sending and receiving at the same time.
13	The SIOP 0 command has been deleted	The SIOP 0 command has been removed.
14	Prevention of panel lock after recovering from auto sleep mode	A Panel lock may occur, while the CD icon is displayed.
15	Preventing key presses of executing when the panel is set to panel lock	After manually locking the Panel, using the Job cancel button was still possible.
16	When feeding from the bypass the leading edge may be faint	When feeding paper from the bypass table, the image leading edge may be faint due to a delayed transfer on timing.