


<b>SB Number:</b>	<b>SB 2H0-007</b>	<b>Creation Date: 12/06/2008</b>
<b>Subject:</b>	<b>Reduce operation panel fan vibration sound</b>	
<b>Model:</b>	<b>KM-2560/3060</b>	

<b>Phenomenon</b>	Some vibration might occur, when the fan at the operation panel section is operating.
-------------------	---


<b>Solution</b>	Attach cushion ope fan (302H005A00) to reduce vibration
-----------------	---

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	302H093143 2H093143	302H093144 2H093144	PARTS OPERATION UNIT EXP	1	1	X	O	O
	2	-----	302H005A00 2H005A00	CUSHION OPE FAN	-	1	-	O	-

Remove the fan, attach cushion ope fan (2) as indicated and reinstall the fan (3).



Check that the cushion is attached as shown in the picture below before refitting the fan.



<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomenon occurs, please attach cushion ope fan (302H005A00).			

Affected serial numbers	Type	Serial number
	KM-2560	QAW8102188 and higher
	KM-3060	QBA8102095 and higher