



SB Number:	SB 2H0-018	Creation Date: 05/02/2009
Subject:	Abnormal noise from paper conveying section 2	
Model:	KM-2540/3040/2560/3060	

Phenomenon	Abnormal noise may occur at paper conveying section 2, when feeding the second sheet of paper from the paper cassette or bypass tray.
-------------------	---

Solution	Apply grease molykote EM-50LP 50G (7BG010009H) at parts roller regist left SP (302H094140) and Bush regist (2C916260).
-----------------	--



Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please apply grease molykote EM-50LP 50G (7BG010009H) at parts roller regist left SP (302H094140) and Bush regist (2C916260)			

Affected serial numbers	Type	Serial number
	KM-2540/3040/2560/3060	September 2008 production