

Model:

LaserBase MF5770

Ref No.:MF5650-011 Rev. 1
(SH-T01-0LD-10032-03)**Date:**

September 2005

Location:

SCNT Board Ass'y

Subject:

Version upgrade of firmware for SCNT board assembly (WLaa-06-02)

SPEED:

SH-LD-0039-01

Destination:

F14-6593 (GB, FR, EUR), F14-6592 (DE)

Reason:

Upgrade the version of firmware for SCNT board assembly from WLaa-05-08 to WLaa-06-02.

History of Upgrade :

Service Bulletin No.	Ver.	Detail	Date
	WLaa-06-02	A bug fix in system timer	28 Jun. 2005
		A fix of bug occurring when conducting remote operation in ESS mode	
		A fix of bug occurring in memory full condition of FAX reception	
	WLaa-05-10	A fix of bug of setting range for autodial	
		A fix of bug causing a lock in manual communication	
		A fix of bug identifying Chinese as ROT incorrectly	
None	WLaa-05-08	First release	

Detail:

Change to WLaa-06-02

No.	Item	Detail
1	A bug fix in system timer	A revision of software to prevent it from causing a bug that a machine becomes inoperative in copying while displaying scanner adjustment 24.85 days after power on
2	A fix of bug occurring when conducting remote operation in ESS mode	A revision of software to prevent it from causing a bug that the Fax reception cannot be done by remote operation with external phone in ESS mode.
3	A fix of bug occurring in memory full condition of FAX reception	A revision of software to prevent it from causing a bug that the last page is not printed in memory full condition of FAX reception.

Change to WLaa-05-10

No.	Item	Detail
1	A fix of bug of setting range for autodial	A revision of software on the setting range for autodial (TYPE: CHINA) "2 to 99" -> "5 to 99"
2	A fix of bug causing a lock in manual communication	A revision of software to prevent it from causing a lock due to communication interruption while printing in manual communication
3	A fix of bug identifying Chinese as ROT incorrectly	A revision of software to prevent it from causing a bug that the machine identifies wrongly Chinese as ROT (re-order tone) in sound detection of switching between FAX and TEL

Service work:

Upgrade the version to Ver.WLaa-06-02 by using "Service Support Tool (SST)" at service visit, or replace SCNT board assembly by new one (FG3-3998-040).

With regard to the usage of "Service Support Tool (SST)", refer to the attached "Service Support Tool (SST) handbook".

Service part:

No.		Part name	Part No.	Qty	Stock	Compatibility	Available from	Fig. No.
1	Old	SCNT BOARD ASS'Y	FG3-3998-000	1 > 0	A	N		950
	New	SCNT BOARD ASS'Y	FG3-3998-040	0 > 1	D	Y		
2	Old	IC,MBM29DL640E90TN-E1,FLASHROM	FH4-4001-000	1 > 0	A	N		950
	New	IC,MBM29DL640E90TN-E1,FLASHROM	FH4-4001-070	0 > 1	D	Y		
3	Old	IC,MBM29DL640E90TN-E1,FLASHROM	FH4-4002-000	1 > 0	A	N		950
	New	IC,MBM29DL640E90TN-E1,FLASHROM	FH4-4002-070	0 > 1	F	Y		

Effective on:

Change to WLaa-06-02

July 2005

Serial No.:

Change to WLaa-06-02

Model	Starting Serial No.
LASERBASE MF5770 (GB)	SFD02161
LASERBASE MF5770 (DE)	SFG02359
LASERBASE MF5770 (FRN)	SHB02801
LASERBASE MF5770 (EUR)	SFM03978

Change to WLaa-05-10

From the first machine of mass production.