

MODEL: LaserBase MF5650

No.: MF5650-001
(SH-T01-0LD-10011-01)
Date: 30.07.04

SUBJECT: PROBLEMS OCCURRING WHEN TRANSMISSION HAS BEEN MADE FROM LASERBASE MF5650 TO TIS-MADE PRODUCT

DESTINATION: F14-5692 (UK, GER, FRN, EUR)

Detail:

<Symptom>

The following problems occur on the LCD of UA1612 (model name) and the communication control report when transmission has been made from LaserBase MF5650 to TIS (manufacturer)-made UA1612.

LCD: The square mark appears continuously following numbers displayed on the LCD of UA1612 (reception side).

(Up to the 20th digit counted from the first number.)

e.g.) 12-3456: 123456□□□□.....

Communication control report: The last number of numbers in the communication control report of UA1612 (reception side) appears continuously. (Up to the 20th digit counted from the first number.)

e.g.) 12-3456: 123456666.....

<Cause>

Software bug.

<Sidestepping Method>

Enter spaces up to the 20th digit (counted from the first number) following valid numbers.

<Factory Measure>

Countermeasures will be taken to software in late July.