

**Model:**

LaserBase MF6530  
LaserBase MF6540PL  
LaserBase MF6550  
LaserBase MF6560PL  
LaserBase MF6580PL

**Ref No.:**

MF6500-003 Rev. 1  
(F9-T01-M00-10005-02)

**Date:**

February 2007

**Location:**

Cassette

**Subject:**


Preventing multiple sheets of paper from being fed simultaneously from cassette

**Detail:**

At the time of cassette pick-up, multiple sheets of paper may be fed at the same time because of too high contact pressure between paper and the pick-up roller. To prevent this, the pressure of the 3 springs [2] that retain the cassette lifter plate [1] is decreased.

The new type spring comes in two types: a blue one and a silver one (See the table below).

Lot number of cassette	Spring color	Part number of spring	Serial number of printer
60707403 and earlier	Silver	FU6-2408-000	Machines with a serial number earlier than the ones listed in "Affected Machines".
60707404 to 61125504	Blue	FU6-2408-020	Machines listed in "Affected Machines"
61125505 and later	Silver		



P-1

P-1 Cassette

[1] Cassette lifter plate

[2] Spring

<Factory measure>

All the 3 springs that retain the cassette lifter plate are changed to the new type.

### Service Work

When the foregoing symptom occurs, replace the 3 springs by the new type simultaneously.

### Service Parts

No.	Part number	Part name	Q'ty	Stock	Compati- bility	Available from	Fig. No.
1	O	FU6-2408-000	SPRING	3 > 0	C	N	300
	N	FU6-2408-020	SPRING	0 > 3	D	Y	

### Affected Machines

LaserBase MF6530 EU1	SNF20166 and later
LaserBase MF6550 EU1	SNG20281 and later
LaserBase MF6540PL EU1	SNP20303 and later
LaserBase MF6560PL EU1	SNQ20236 and later
LaserBase MF6580PL EU1	SNR20969 and later
LaserBase MF6530 EU2	SNX20225 and later
LaserBase MF6550 EU2	SPB20168 and later
LaserBase MF6540PL EU2	SPC20226 and later
LaserBase MF6560PL EU2	SPD20274 and later
LaserBase MF6580PL EU2	SPF20290 and later
LaserBase MF6550 EU3	SPG20365 and later
LaserBase MF6560PL EU3	SPH20055 and later
LaserBase MF6580PL EU3	SPJ20408 and later