

**Model:**

LaserBase MF6530  
LaserBase MF6540PL  
LaserBase MF6550  
LaserBase MF6560PL  
LaserBase MF6580PL

**Ref No.:**

MF6500-023  
(F9-T01-M00-10046-01)

**Date:**

February 2009

**Location:**

Software

**Subject:**

System software WLaa31-01 release

**Reason:**

To upgrade Main for quality improvement

[System CD-ROM No.]

GM08-1928 (FY9-4268-020): MF6500 Series System WLaa31-01

**Details:**

1. Changes made when upgrading Main Ver. WLaa13-01 to WLaa31-01

No.	Description
1-1	Modification of the failure that binding position is not correct in duplex printing with PCL. (C-Walk No.: F9C02M001001201)
1-2	Modification of the failure that character position is displaced in printing with PCL. (C-Walk No.: F1C010M41138901)

2. Changes made when upgrading Main Ver. WLaa08-01 to WLaa13-01

No.	Description
2-1	Modification of the failure that wrong GMT time is displayed; summertime setting concerned. (C-Walk No.: F1C01N001001901)
2-2	Modification of the failure that RUI hangs and freezes; occurs when accessed from PC with Windows Vista and IE7. (C-Walk No.: F1C01N001001201)

**Version Configuration:**

The operating guarantee is undertaken for the following combination.

Boot	Main	OPT16
WLaa13-01	WLaa31-01	WLaa31-01

**Affected Machines:**

To be informed as soon as identified.

## &lt;History of Release&gt;

Service Info No. / System CD-ROM Part No. / Date	Ver. No./ Modifications
- / GM08-1928 (FY9-4268-020) / February 5, 2009	Main WLaa31-01/ OPT16 WLaa31-01 - Modification of the field claim (2 items)
- / GM08-1928 (FY9-4268-010) / -	Main WLaa13-01 - Modification of the field claim (2 items)
F9-T01-M00-10014-01 / - / September 5, 2006	System WLaa8.01/ Boot WLaa8.01/ ECONT MT0904 - Change of specifications (2 items)
-	System WLaa7.04/ Boot WLaa7.04/ ECONT MT0904 First release