

SB Number:	SB DF-068	Creation Date: 16/04/2009
Subject:	<i>Additional service call C-8140 reason/measure (main tray problem)</i>	
Model:	DF-71/710	

Affected models: DF-71: FS-9100DN/9120DN/9500DN/9520DN
DF-710: FS-9130DN/9530DN

Contents of changes	<p>Service call C-8140 (main tray problem) reason/measure are described on page 46 of the service manual.</p> <p>Please note that service call C-8140 also occurs, when spring, holder main eject pull 303C106062 comes off from spring holder sol 303JY28340.</p>
----------------------------	--

Fig. 4 Exit section

