

<b>SB Number:</b>	<b>SB 3JY-002</b>	<b>Creation Date: 11/02/2008</b>
<b>Subject:</b>	<b>Firmware change, new model support</b>	
<b>Model:</b>	<b>DF-710/730, DP-710</b>	







The firmware for DF-710 and DP-710 has been changed to support KM-C4035E.

The firmware for DF-730 has been changed to support KM-2560/3060/2540/3040 and KM-C4035E.

**NOTE:**

The below table describes the compatibility between current and new machines/accessories.

The newer DF-710/730 and DP-710 are compatible with the KM-C4035E.

	Compatible with present model			Support for new model		
Main body to which it can be installed	KM-C2520/C3225/C3232 KM-C2525E/C3232E			KM-C4035E DF 730 supports KM-2560/3060/2540/3040.		
Label on the outer carton						
Item code:	DF-710 1203JY3UT0	DF-730 1205H13UT0	DP-710 1203J93UT0	DF-710 1203JY3U10	DF-730 1205H13U10	DP-710 1203J93U10

DF-710								
No.	Old Parts No.	New Parts No.	Description	Q'ty		Interchange ability		Firmware version.
				Old	New	Old	New	
1	303JY01022 3JY01022	303JY01023 3JY01023	MIDDLE PWB ASS'Y	1	1	X	O	3JY_9600.004.002
2	303JY80014 3JY80014	303JY80015 3JY80015	MAIN PWB ASS'Y WITH SOFTWARE SP	1	1	X	O	3JY_9200.006.003

DP-710								
No.	Old Parts No.	New Parts No.	Description	Q'ty		Interchange ability		Firmware version.
				Old	New	Old	New	
1	303J901011 3J901011	303J901012 3J901012	DRIVER PWB ASS'Y	1	1	X	O	3J9_9500.004.005

DF-730								
No.	Old Parts No.	New Parts No.	Description	Q'ty		Interchange ability		Firmware version.
				Old	New	Old	New	
1	305H180020 5H180020	305H180021 5H180021	PBA-CONT-F	1	1	X	O	5H1_9200.002.007

Affected machine serial numbers		
Model	Item code	Start serial number
DF-710	1203JY0U10	PRA7508105 and higher
	1203JY3U10	PNP7502090 and higher
DF-730	1205H10U10	URF7412474 and higher PRK*****1 and higher
	1205H13U10	UNN*****1 and higher PNX*****1 and higher
DP-710	1203J95J10	PVM7507511 and higher
	1203J90K10	PAQ7517537 and higher
	1203J93U10	PNN7503761 and higher

Contents of changes in firmware			
	Model	Item	Contents
1	DF-710 DF-730 DP-710	Support for KM-C4035E.	Changed the conveying speed.
2	DF-710	The timing of paper holding solenoid has been adjusted.	In order to reduce the sound of the paper holding lever hitting the main tray, the operation timing of the paper holding solenoid has been changed.
3	DF-710	Method to prevent JAM 88 (Main tray eject JAM).	There is a possibility that JAM88 might occur when copying 3 sheets monochrome A4 copies with 2 staples continuously.
4	DP-710	The paper feeding timing when using the Auto select function has been changed.	When using the Auto select function, there is a possibility that small sized originals are detected as large sized originals and the copy image is printed half on the large sized paper.