

SB Number:	SB 3JY-003	Creation Date: 17/04/2008
Subject:	System firmware upgrade version 002.009	
Model:	DF-730	

Contents of changes	Item	Contents
	1	Abnormal noise from reverse section. The finisher reverse roller activates before paper has completely gone through the last roller of the machine. Therefore the timing has been changed so that the DF-730 feeds the paper after it has completely passed the last roller of the machine.
	2	Motor alignment error C8170. After Jam 81 the Print job does restart, however an alignment motor error could occur when the first sheet of the restarted print job ejects from the machine to the DF-730. This is because the alignment motor stops, instead of initializing after Jam 81.

Latest firmware for KM-2560/3060/2540/3040 as of October 2007	Type	Program No.	Check SUM	Version	Status Date
	MAIN (IPU)	5H1_9200.002.009	0454	002.009	

Note	See SB 3JY-002 if it is necessary to replace PBA-CONT-F								
Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	305H180021 5H180021	305H180022 5H180022	PBA-CONT-F	1	1	X	O	O

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When above mentioned phenomena occurs, please upgrade the firmware to the newest version.			

Affected serial numbers	Type	Serial number
	DF-730	PRK7X00001 and higher