

SB Number:	SB DF-068	Creation Date: 16/04/2009
Subject:	Additional service call C-8140 reason/measure (main tray problem)	
Model:	DF-35/71/710/760	

Affected models: DF-35: KM-C830/830D
 DF-71: KM-2530/3530/4030/3035/4035/5035
 DF-710: KM-3050/4050/5050, KM-C2520/3225/3232/2525E/3232E/4035E
 DF-760: TASKalfa250ci/300ci/400ci/500ci

Contents of changes Service call C-8140 (main tray problem) reason/measure are described on page 46 of the service manual.
 Please note that service call C-8140 also occurs, when spring, holder main eject pull 303C106062 comes off from spring holder sol 303JY28340.

Fig. 4 Exit section

