


SB Number:	SB 2H9-006	Creation Date: 15/09/2010
Subject:	Improving the adhesive material of the pad front SEP	
Model:	FS-1028MFP/DP, FS-1028MFP/3040MFP/3140MFP, FS-C2026MFP/2126MFP, DP-110	

Affected models:	DP-110	FS-1028MFP/DP, FS-1028MFP/1128MFP/3040MFP/3140MFP, FS-C2026MFP/2126MFP
------------------	--------	---

Phenomenon	The pad front SEP may disengage from the paper feed guide (upper guide B) .
Cause	When removing the original to clear a paper jam at the DP, the pad front SEP may peel off.
Solution	To improve the adhesive strength, the material of the double faced tape surface of the pad front SEP has been changed from 5000NS to TW-Y01 type .



Parts

No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
				Old	New	Old	New	
1	303K507101 3K507101	303K507102 3K507102	PAD FRONT SEP	1	1	O	O	O

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please replace the pad front SEP with the latest type.			

Serial numbers of affected machines

Type	Serial number
FS-1028MFP/DP, FS-1028MFP/3040MFP/ 3140MFP, FS-C2026MFP/ 2126MFP	August 2010 production.

Machines produced after the above mentioned production date, should not have the above mentioned phenomenon.

Serial numbers of affected units

Type	Serial number
DP-110	August 2010 production.

Units produced after the above mentioned production date, should not have the above mentioned phenomenon.