

SB Number:	SB DP-021	Creation Date: 14/08/2009
Subject:	<i>Additional measures to prevent wire interface damage</i>	
Model:	DP-670	

Affected models: KM-2540/3040/2560/3060

Phenomenon	The wire interface between the DP-670 and the main body may be damaged, when opening and closing the DP-670.
-------------------	--


Solution	<p>The following changes have been made:</p> <ol style="list-style-type: none"> 1. The shape of the base DP has been changed. 2. The shape of the cover rear has been changed. 3. The length of the wire interface has been extended with 20mm. <p>(See service bulletin DP-009 for the previous measure)</p>
-----------------	--

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	303K502010 3K502010	303K502011 3K502011	BASE DP	1	1	O	O	-
	2	303K504020 3K504020	303K504021 3K504021	COVER REAR	1	1	O	O	O
	3	303K546052 3K546052	303K546053 3K546053	WIRE INTERFACE	1	1	O	O	O



Classification	<input type="checkbox"/> Entire stock rework <input type="checkbox"/> In-field modification at next visit <input checked="" type="checkbox"/> In-field modification by case <input type="checkbox"/> No modification necessary
Field measure	<p>Make sure that the wire interface is not twisted when installing it. (see service bulletin DP-009)</p> <p>Please note that old and new parts can be mixed, this however will not ensure that the wire interface will remain undamaged when opening or closing the DP-670.</p>

Affected serial numbers	Type	Serial number
	DP-670	Not available

Item 1; New shape of the base DP



Item 2; New shape of the cover rear



*1; Back view of the cover rear

