


<b>SB Number:</b>	<b>SB DP-014</b>	<b>Creation Date:</b> 27/11/2008
<b>Subject:</b>	<b>Double paper feed when feeding from the DP-670</b>	
<b>Model:</b>	<b>DP-670</b>	

Affected models: KM-2540/3040/2560/3060

<b>Phenomenon</b>	Paper may be fed double from the DP-670. This will most likely occur when feeding one of the last originals.
-------------------	-----------------------------------------------------------------------------------------------------------------

<b>Cause</b>	Friction between the friction plate and paper.
--------------	------------------------------------------------

<b>Solution</b>	The material of the friction plate located at the lower guide paper feed (3HL07070) has been changed from fibre fabric to cork pad.
-----------------	-------------------------------------------------------------------------------------------------------------------------------------



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	3HK07240	2A107060	FRICION PLATE,CASSETTE	1	1	X	O	O

<b>Classification</b>	<input type="checkbox"/> Entire stock rework <input type="checkbox"/> In-field modification at next visit <input checked="" type="checkbox"/> In-field modification by case <input type="checkbox"/> No modification necessary
<b>Field measure</b>	When the above mentioned phenomenon occurs, please replace friction plate cassette 3HK07240 with 2A107060. Please be aware that noise may be generated initially, if the outside environment has high humidity and/or temperature. This however will decrease after more paper is fed from the DP-670.

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	DP-670	September 2008 production