



KYOCERA Service Bulletin

SB Number:	SB DP-018	Creation Date: 18/02/2009
Subject:	Firmware upgrade (preventing skewed duplex scanning)	
Model:	DP-710	

Affected models: KM-C2520/3225/3232/2525E/3232E/4035E

Contents of changes	Item	Contents
	1 Skewed scanning of originals in duplex mode.	Originals may be scanned skewed in duplex mode. The loop amount has been changed to prevent this from occurring.

Solution; replace the driver PWB ass'y 303J901012 with driver PWB ass'y 303J90104



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	303J901012 3J901012	303J901014 3J901014	DRIVER PWB ASS'Y (F/W version 9500.006.002)	1	1	○	○	○

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please replace the driver PWB ass'y 303J901012 with driver PWB ass'y 303J90104 and upgrade the firmware to the latest version.			

Affected serial numbers	Type	Serial number
	DP-710	August 2008 production