

<b>SB Number:</b>	<b>SB 2BX-001</b>	<b>Creation Date:</b> 16/12/2003
<b>Subject:</b>	System firmware upgrade	
<b>Model:</b>	<b>FS-1010 / 1050</b>	

Please be informed that the system firmware for the FS-1010 / 1050 has been changed as follows.

## CONTENTS OF CHANGES

- ✓ New parameter FRPO o2=9 has been added to enable 'paper empty' control. A similar PE signal and data receiving control has been added as in the previous model FS-1000.
- ✓ When printing a PCL file after downloading several PCL fonts, font selection might not be correct and the font lastly downloaded is selected.

In compliance with the change of firmware, the Mask ROM type and DIMM board have been changed. As a result, also the part code has changed as follows.

**Field Measure:** If phenomena arises please change the system DIMM.

	Version	Checksum	Label name	U-no.	Rom type
System	80.06	0900	S93K8006	YS01	4MB-DIMM

Part No. OLD	Part No. NEW	Description OLD	Description NEW	Q'ty old-new		Interchange ability		Remarks
5AAPRMEG2011HQ	2BX01200	P.W.B. ASSY KP-854	P.W.B. ASSY KP-893	1	1	O	O	PWBA/D

### Affected Machine Serial Numbers:

**FS-1010:** from XAL3X89428 to XAL3X91168 / XAL3Y93199 and later  
**FS-1050:** from next production.