

<b>SB Number:</b>	<b>SB 2BX-005</b>	<b>Creation Date:</b> 08/12/2005
<b>Subject:</b>	<b>System firmware upgrade, version 80.07</b>	
<b>Model:</b>	<b>FS-1010/1050</b>	

The System firmware is upgraded as follows:

**The contents of main changes**

	Phenomenon	Contents
1	Attribute on CF with API can not be read	The wrong calculation of attribute addresses has been corrected.
2	Output error occurs with Acrobat 6.0 data	The process after the error for the filter comes out has been corrected.
3	Possibility of lock with KPDL2	The accuracy of the error margin has been increased as a lock occurred because of the error margin.

Type	Program number	Check SUM	Version	Remarks
System	---	2300	80.07	-

According to the firmware change, the below mentioned parts are changed.

No.	Old parts number	New parts number	Description	Q'ty		Interchangeability		SP	Remarks
				Old	New				
1	2BX01200	2BX01201	P.W.B ASSY KP-893	1	1	○	○	○	

**Field Measure:**

If the problem arises, please upgrade firmware

**Affected machine serial numbers:**

**FS-1010**

XAL4Z39011 and higher

**FS-1050**

(No production currently)