

SB Number:	SB 2DD-002	Creation Date: 22/11/2004
Subject:	Firmware upgrade	
Model:	FS-1018MFP	

Please be informed that the main firmware for FS-1018MFP has been upgraded as follows.

MAIN **Ver. 2DD_2000.002.006**

CONTENTS OF CHANGES

	Contents	Remarks
1	Default value of centerline position adjustment for Cassette 1 (item in U048) has been changed from [571] to [579].	---
2	Adding "second" description to date file name.	When adding a time description to a job name (Scan To E-mail, Panel job name, Job end report etc.) the description "second" will be added to the file name in addition to "date", "time" (and "minute").
3	Changing the process for Warning Buzzer	Error sound takes priority over job end sound. If an error message is displayed, a process has been added so that the job end sound is not heard even if job end notification is sent.
4	If bulk data is sent from FTP client, output is stopped.	The phenomenon has been corrected in the F/W.
5	If LAN cable is accidentally pulled out during transmission, CF426 occurs after the occurrence of Send Error 2202	The phenomenon has been corrected in the F/W.
6	If maintenance mode U065 (= Adjusting the scanner magnification) is changed from the default value "0", image may be incorrect.	<u>Incorrect image:</u> 1. If originals are scanned through DP when 'Continuous Scan' is turned on and the top side of the originals is placed to the back side of machine, white sheets of paper may be output. 2. If '4 in 1 output' is performed, unusual image (solid black image etc.) may appear. 3. If the default value is set to a minus value, scan copy through DP is output as white sheets of paper.
7	Option language support	Extra optional language is supported from Main F/W version 2DD_2000.002.006" or later. (for more details, see SB 2DD-001)

Additional note:

The message that notifies that the waste toner bottle is nearly full may not disappear, even though old Process Unit is replaced with new Process Unit. Please be informed however that the message will disappear after approximately 200 sheets are printed. The remaining of the message on the display does not have any influence on performance or function of the machine.

Firmware details (Main)

Type	Program No.	File Name	Check SUM	
MAIN (CONTROLLER)	2DD29911	S2DD_2000002006.zip	----	2DD_2000.002.006
LCD (PANEL)	----	----	----	2DD_A000.001.019

Field Measure

Firmware upgrade can be done with CF card. For procedure, see chapter **1-7-1** of the service manual. The firmware file 2DD_2000.002.006 and all available optional language files can be downloaded from MFP & Printer Reserved website accessible via <http://www.kmissupport.com>.

Affected Machine Serial Numbers:

FS-1018MFP: XLA4805125 and later