

SB Number:	SB 2DD-003	Creation Date: 31/01/2005
Subject:	Change of 'P.W.B ASSY MAIN'	
Model:	FS-1018MFP	

Phenomenon & Cause

When executing [**Printer reset**] from the printer menu on the operation panel, after the reset, there is the possibility that network may remain in '*pending / suspension*' status.
(If the PHY chip is in its energy save mode, the return signal sent via a different way than the network is not output and the network might remain in pending status.)

CONTENTS OF CHANGES

By changing the following constant of '**PCB PRINTER ASSY**' in energy save mode, the PHY chip will output a signal even if the reset is triggered via a different way than over the network.

- R213: OLD 100K Ω → NEW: 0 Ω
- C219: OLD 0.1 μ F → NEW: not mounted

Field Measure

If the problem should arise, please replace the current with the new '**PCB PRINTER ASSY**'.

Parts Table

No.	Part No. OLD	Part No. NEW	Description	Q'ty		Interchangeability	
				Old	New		
1	302DD68111 2DD68111	302DD68112 2DD68112	P.W.B ASSY MAIN EU (SP)	1	1	X	O

Affected Machine Serial Numbers:

FS-1018MFP: will follow