



SB Number:	SB 2HS-005	Creation Date: 04/08/2009
Subject:	<i>Paper jam at the registration sensor can not be cleared</i>	
Model:	FS-1100/1300D/1350DN	

Phenomenon	A paper jam at the registration sensor is not cleared after removing the paper.
-------------------	---

Cause	A piece of paper is torn off and is trapped at the frame MFP 302HS08010.
--------------	--

Solution	<p>The following changes have been made:</p> <ol style="list-style-type: none"> 1. Cover reg SW 302HS08340 has been added to the frame MFP. 2. Spring pressure of spring cover REG 302HS08351 has been changed from 3 GF to 24 GF. 3. Based on the above mentioned change, the shape of the frame MFP 302HS08011 has been changed.
-----------------	---



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
	1	302HS08010 2HS08010	302HS08011 2HS08011	FRAME MFP	1	1	O	O	O
	2	-----	302HS08340 2HS08340	COVER REG SW	-	1	-	O	O
	3	302HS08350 2HS08350	302HS08351 2HS08351	SPRING COVER REG	1	1	O	O	O

Affected serial numbers	Type		Serial number	
	FS-1100		XLZ9464711 and higher	
	FS-1300D		XLY9246747 and higher	
	FS-1300DN		XET9214900 and higher	