

SB Number:	SB 2GM-004up	Creation Date: 13/04/2007
Subject:	Firmware upgrade, Ver. 006.001 (system)	
Model:	FS-1118MFP	

Firmware is upgraded as follows.

- The spelling of the descriptions in the network status page have been corrected:
 = Defind -> Defined
 = Not Defind -> Not Defined
- IP Filter is defined differently by protocol. This has been implemented as a new feature.
- Lock-up at power-up diagnosis has been corrected

Due to a change in the NVRAM mapping, custom settings such as country settings and network settings are reset when downgrading the firmware from 2GM_2000.006.001 or 005.005 to version 2GM_2000.004.008 or older.

The effect of firmware updates are as follows. Please use this as a guide when up- or downgrading firmware in order to avoid problems:

Before update	After update	Comment
up to 004.008	004.008 and earlier	No problem
	005.005	DO NOT UPDATE
	006.001 and later	No problem
005.005	004.008 and earlier	DO NOT UPDATE
	005.005	No problem
	006.001 and later	No problem
006.001	004.008 and before	DO NOT UPDATE
	005.005	No problem
	006.001 and later	No problem

Firmware specifications

Type	Program number	Check SUM	Version
SYSTEM	2GM_2000006001	3796	006.001

Previous version: 004.008

Serial number information:

Machines with serial number XLK7278869 and higher have firmware version 006.001 installed at the factory and no problems are expected for these machines.