

SB Number:	SB 2FP-003	Creation Date: 15/06/2004
Subject:	Upgrade of engine (A002) and system (158.03) firmware	
Model:	FS-3820N, FS-3830N	

Please be informed that the system and engine firmware for the FS-3820N/3830N has been changed as follows.

SYSTEM FIRMWARE

Version 158.02 ⇒ **158.03**

CONTENT OF CHANGE

Failure occurred when printing e-mail with file attachments compressed by QUOTED PRINTABLE.
F/W has been changed to correct this.

FS-3820N / 3830N

	Version	Checksum	Label name	U-no.	Rom type
System	158.03	4CD0	SB21K15803	YS1	4MB-DIMM

Affected Machine Serial Numbers, version 158.03:

FS-3820N: VLD4304898 and later
FS-3830N: ALC4303351 and later

ENGINE FIRMWARE

Version A001 ⇒ **A002**

CONTENT OF CHANGE

Printer may produce faint print at low temperature. F/W has been changed to correct this.

FS-3820N

	Version	Checksum	Label name	U-no.	Rom type
Engine	A002	A204	EB28KA002	U2	2Mbit-Flash

FS-3830N

	Version	Checksum	Label name	U-no.	Rom type
Engine	A002	9FA8	EB21KA002	U2	2Mbit-Flash

Affected Machine Serial Numbers, version A002:

FS-3820N: ALD4406393 and later
FS-3830N: ALC4405701 and later