

SB Number:	SB 2F8-001	Creation Date: 06/06/2006
Subject:	Firmware upgrade, Ver. 003.003 (engine)	
Model:	Fs-2000D, FS-3900DN	

The firmware is upgraded to correct the following phenomena:

SITUATION:

Paper is put on the MP tray and drum refresh mode is executed.

PHENOMENON:

If the top cover is opened and closed while indicating "Please wait" (after outputting paper), the operation panel subsequently displays "Ready" but a paper jam occurs at next printing nonetheless.

FS-2000D

Type	Program number	Check SUM	Version	Remarks
ENGINE	S2F8_1000003003	1FF3	003.003	-

FS-3900DN

Type	Program number	Check SUM	Version	Remarks
ENGINE	S2F9_1000003003	A8F1	003.003	-

Field Measure:

If the problem arises, please upgrade firmware.

Affected machine serial numbers:

FS-2000D: XLM6306569 and higher

FS-3900DN: XLN6200339 and higher