

SB Number:	SB 2F8-006	Creation Date: 02/08/2006
Subject:	Firmware upgrade, Ver. 005.002/006.001 (engine/system)	
Model:	FS-3900DN	

Engine firmware (Ver. 005.002)

1. A paper jam (fuser unit) sometimes occurred when OHP sheets were output on the FD tray;
2. When printing to the FU tray and the messages "Printing " and "Ready" are repeated 25 times without switching the power off/on, the following job will not be printed though the LCD panel will display "Processing".

TYPE	Program number	Check SUM	Version
ENGINE	S2F9_1000005002	BEB4	005.002

System firmware (Ver. 006.001)

Engine firmware is now available for download through network.

TYPE	Program number	Check SUM	Version
SYSTEM	S2F9_3000.006.001	B704	006.001

Field measure:

If the problem arises, please upgrade firmware.