

| | | |
|-------------------|--|----------------------------------|
| SB Number: | SB 2F8-003 | Creation Date: 10/07/2006 |
| Subject: | Firmware upgrade, Ver. 003.003 (ENGINE) | |
| Model: | FS-2000D, FS-3900DN | |

Firmware is upgraded to correct following.

- When paper is put on MP Tray the drum refresh mode is executed.
- If the top cover is opened and closed whilst indicating "Please wait" after outputting paper, the operation panel will display "Ready" but a paper jam occurs on the next job.

FS-2000D

| Type | Program number | Check SUM | Version |
|--------|-----------------|-----------|---------|
| ENGINE | S2F8_1000003003 | 1FF3 | 003.003 |

Current Version: 002.007

FS-3900DN

| Type | Program number | Check SUM | Version |
|--------|-----------------|-----------|---------|
| ENGINE | S2F9_1000003003 | A8F1 | 003.003 |

Current Version: 002.007

Field measure:

If the problem arises, please upgrade firmware.

Affected machine serial numbers:

FS-2000D: XLM6306569 and higher

FS-3900DN: XLN6200339 and higher