

KYOCERA Service Bulletin



SB Number:	SB 2J0-003	Creation Date: 24/06/2009
Subject:	Abnormal sound from the FD unit at the exit section	
Model:	FS-2020D/3920DN/4020DN/6950DN	

Phenomenon	Abnormal sound may arise from the FD unit at the exit section, when printing in duplex.
-------------------	---

Solution	Quick drying lubricant "PD-910" has been applied to the shaft eject pulley of the pulley feed.
-----------------	--

FS-2020D/3920DN/4020DN

FS-6950DN/6970DN



 = Surface where the PD-910 lubricant has been applied.

 = Surface where the PD-910 lubricant has been applied.

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please apply PD-910 lubricant to the shaft eject pulley.			

Affected serial numbers	Type	Serial number
	FS-2020D/3920DN/4020DN/6950DN	May 2009 production