

SB Number:	SB 2BZ-004	Creation Date: 06/04/2004
Subject:	Dog ear in paper (Fuser unit change)	
Model:	FS-6020 (FK-400)	

### Phenomenon

Dog's ear in the ejected paper.


### Countermeasure

The material and shape of the 'GUIDE PAPER FUSER L/R' has been changed.  
 The shape of both the 'GUIDE PAPER FUSER L' and 'GUIDE PAPER FUSER R' has been unified to improve the productivity and the work efficiency.

### Contents of changes

Material change

OLD: resin / NEW: sheet metal



### Parts Table

No.	Part No. OLD	Part No. NEW	Description	Q'ty old-new	Interchange ability
1	-----	2BZ20290	GUIDE FUSER L	- 2	- O
2	2BZ20250	-----	GUIDE PAPER FUSER L	1 -	O -
3	2BZ20260	-----	GUIDE PAPER FUSER R	1 -	O -

### Affected Machine Serial Numbers:

FS-6020: AAS3602354 and later  
 FK-400: GMD3610632 and later