

SB Number:	SB 2HG-004	Creation Date: 19/11/2009
Subject:	<i>Firmware upgrade (changed drum refresh modes)</i>	
Model:	FS-C5400DN	

Contents of changes	Item	Contents
	Changed drum refresh modes.	<p>The drum refresh modes have been changed as follows:</p> <p>SVEG 78 : 0 (default setting)</p> <ol style="list-style-type: none"> 1. Drum refresh for 30 sec activated at humidity -5%RH 2. Drum refresh for 30 sec activated at humidity -10%RH 3. Drum refresh for 30 sec. always at start-up (also after sleep mode recovery). 4. Drum refresh of normal mode always at start-up (also after sleep mode recovery). <p>RH = relative humidity</p>

Firmware	Type	Program No.	Check SUM	Version	Status Date
	ENGINE	2HG_1000004004	fe9b	004.004	22/07/2009

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	Upgrade the firmware to the latest version, to implement the new drum refresh modes.			

Serial numbers of affected machines

Type	Serial number
FS-C5400DN	XAC9800467

Machines produced after the above mentioned serial number, are affected by the above mentioned change.