

SB Number:	SB 2HG-003	Creation Date: 19/11/2009
Subject:	<i>Firmware upgrade (sleep timer delay and error code F186)</i>	
Model:	FS-C5400DN	

Contents of changes	Item	Contents
	1 Delay when setting the auto sleep timer.	When setting the sleep timer, the timing may be delayed with 36 seconds, due to ASIC setting error. (e.g. timer is set to 4 hours, the auto sleep mode is activated 36 seconds later)
	2 Processing lock or error code F186.	A processing lock or error code F186 may occur when using a DIMM which is not listed in the guide line.

Firmware	Type	Program No.	Check SUM	Version
	SYSTEM	2HG_3000003001	2787	003.001

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomena occur, please upgrade the firmware to the latest version.			

Serial numbers of affected machines

Type	Serial number
FS-C5400DN	XAC9800467

Machines produced after the above mentioned serial number, should not have the above mentioned phenomena.