

KYOCERA Service Bulletin

SB Number:	SB PF-018	Creation Date: 01/10/2009
Subject:	Abnormal noise at the multi purpose feeder	
Model:	PF-500/510	


Affected models: FS-C5100DN/5200DN/5300DN/5400DN

Phenomenon Abnormal noise may arise from the gears at the multi purpose feeder.

Solution The following changes have been made:

1. The material of gear joint Z13 (303K09320) has been changed.
2. Grease has been applied at the back of cover lift gear (303K809120) and at the bearing side of the paper cassette.

Phenomenon; Gear Z13 generates noise at the multi purpose feeder



Solution; Grease has been applied at the bearing part of the paper cassette.



Solution; Grease has been applied at the cover lift gear.



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	303K809320 3K809320	303K809321 3K809321	GEAR JOINT Z13	1	1	O	O	O