

Service Bulletin

SB Number:	SB DF-052	Issue Date: 22/02/2002
Subject:	Vibrating sound during last fed sheet through STDF-3	
Model:	STDF-3 (for KM-1530 / 2030 / 2530)	

Phenomenon

When feeding an original through the STDF-3, a vibrating sound may be heard when last original is being fed. (This however has no effect on the image quality)

Cause


Play at the original feed cover.

Field measure


Install a shim (10.2x 15 x 1, P/N: C2896130) at the front and rear hook of the original feed cover in order to prevent the vibration (for one unit there are 2 shims needed).

See below fig: detach the hook and insert a shim.

Insert a shim (10.2 x 15 x 1)



Front Hook part



Rear Hook part

The shims have already been installed in following machines:

STDF-3: 37012842 and later