

SB Number:	SB 2C9-033	Creation Date: 12/06/2008
Subject:	Black or white lines due to dust	
Model:	KM-1620/2020/1650/2050/2550	


Phenomenon	Black or white stripes may appear on the image.
-------------------	---

Cause	Dust that is sucked in by the right fan may contaminate the main charger/LSU right or slit glass.
--------------	---


Solution	<p>Add Duct right (302C904600) and filter right (302C904610) over the position of the right fan on the outside of the machine, to prevent dust from getting into the machine..</p> <p>See instructions below.</p>
-----------------	---

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	-----	302C904600 2C904600	DUCT RIGHT	-	1	-	X	-
	2	-----	302C904610 2C904610	FILTER RIGHT	-	1	-	X	O

With the notch of the duct right pointed downwards, hook the 4 claws onto the right side of the machine as indicated.



Install the filter right under the 6 claws of duct right.



Field measure	Depending on the machines environment, install duct right and filter right on the machine.
----------------------	--