


SB Number:	SB 2C9-011	Creation Date: 01/10/2004
Subject:	Improvement of 'STRAP LEFT COVER A/B'	
Model:	KM-1620 / 2020	

The way of fixing the '**STRAP LEFT COVER A/B**' (No.1, No.2) has been changed so that the strap attached to the back side of '**LEFT COVER**' (P/N: 2C904050) does not come off easily.

CONTENTS OF CHANGES

- 1) The fixation of '**STRAP LEFT COVER A/B**' has been changed from '**PIN STRAP**' (No.4) to '**CUT WASHER 5**' (No.3).
- 2) In compliance with change 1, the shape of the '**STRAP LEFT COVER A/B**' has been changed as well.


NEW shape of 'STRAP LEFT COVER A/B'



NEW way of fixation:

Fit the 'CUT WASHER 5' into the groove at the end of 'STRAP LEFT COVER A/B' and fix.

OLD shape of 'STRAP LEFT COVER A/B'



OLD way of fixation:

Insert 'PIN STRAP' into the hole in 'STRAP LEFT COVER A/B' and press down the strap with plastic holder ('A' part) and fix.

Parts Table

No.	Part No. OLD	Part No. NEW	Description	Q'ty		Interchange ability	
				Old	New		
1	2C904230	2C904231	STRAP LEFT COVER A	1	1	X	X
2	2C904240	2C904241	STRAP LEFT COVER B	1	1	X	X
3	-----	2C904550	CUT WASHER 5	-	2	-	X
4	2C904420	-----	PIN STRAP	2	-	X	-

When replacing old with new parts, please replace no 1 through 3 at the same time.

Affected Machine Serial Numbers:

KM-1620: H3052323 and later
KM-2020: V3006293 and later