

KYOCERA Service Bulletin

SB Number:	SB 2C9-036	Creation Date: 18/02/2009
Subject:	Black band through the image	
Model:	KM-1620/2020/1635/2035/1650/2050/2550	

Phenomenon	A black band may occur on the print-out.
-------------------	--

Cause	The film terminal main may condensate under the condition of a environment with a high degree of temperature/humidity. This may then result in leaking of the electrical charge at the edge section of the terminal main.
--------------	--

Solution	Improve the isolative capability of the terminal main, by adding a film (sheet terminal main 302FT26050) to the terminal main.
-----------------	--



Phenomenon; A black band appears on the image



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
					Old	New	Old	New	
	1	-----	302FT26050 2FT26050	SHEET TERMINAL MAIN	-	1	-	O	O



Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please add sheet terminal main 30FT26050 under the film terminal main.			

Affected serial numbers	Type	Serial number
	KM-1620/2020/1635/2035/1650/2050/ 2550	November 2008 production



Cause; Under high temperature/humid environment condition, electrical charge may leak from the main charger.

Sheet terminal main 302FT26050 details



Solution; Add sheet terminal main at the back of the base terminal main

