

SB Number:	SB 2JB-010	Creation Date: 01/04/2010
Subject:	Firmware upgrade (error code 00, added security level etc.)	
Model:	KM-2540/3040, Printing system (Y)	

Item	Contents
1 "Error code 00" (normal completion) after completing maintenance mode U411 (automatic scanner adjust) successfully.	"Error code 00" may be displayed after completing maintenance mode U411 successfully. This message has been changed to "RESULT OK 00" to indicate that U411 has been completed without problems.
2 The security level has been added.	The security level can be set to high or low as follows: System Menu/Counter → Machine default → Security level → (change the set value) → Input password → Choose low or high
3 Improper counter clearing at the account ID of the accounting system.	It may be possible that 1 count is added to the copy count, before clearing the counter at the accounting ID of the accounting system.
4 Numonyx flash memory.	The firmware has been changed to support the latest Numonyx flash memory.

Firmware

Type	Program No.	Check SUM	Version
MAIN	2JB_2000005011	----	005.011
ENGINE	2JB_1000014003	----	014.003
LANGUAGE E	2JB_81XE002001	----	002.001
PRINTER FS	2JB_3F00005002	----	005.002

Parts

No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
				Old	New	Old	New	
1	303LG94010 3LG94010	303LG94011 3LG94011	PARTS PWB DIMM ASS'Y WITH SOFTWARE SP	1	1	X	O	O

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input checked="" type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomena occur, please upgrade the firmware to the latest version.			

Serial numbers of affected machines

Type	Serial number
KM-2540/3040	November 2009 production

The above mentioned changes have been applied to machines produced after the above mentioned production date.

Serial numbers of affected units

Type	Serial number
Printing system (Y)	December 2009 production

The above mentioned changes have been applied to units produced after the above mentioned production date.