

SB Number:	SB 2JB-001	Creation Date: 04/02/2008
Subject:	<i>Upgrading Firmware (Can not use the DP after receiving a FAX in sleep mode)</i>	
Model:	KM-2540/3040	

Contents of changes		
	Item	Contents
1	Can not use the DP after receiving a fax in sleep mode	After pressing the power key to return from sleep mode the document processor does not feed the original.
2	Correcting the maintenance report	Maintenance items which are not for field service have been removed from the Maintenance report.

Latest firmware as of December 2007			
Type	Program Number	Check SUM	Version
MAIN	2JB_2000003001	4F85	003.001
ENGINE	2JB_1000004001	AE2C	004.001
LANGUAGE E	2JB_81XE001003	6FB3	001.003
PRINTER FS	2JC_3F00.002.001	147D	002.001
FAX	3LH_5100002002	604D	002.002
For FAX remote	R3LH_5100002002	----	002.002

Field Measure: At installation of the fax system or in case the fax is standard, upgrade the firmware.

Affected Machine Serial Numbers:	
KM-2540	QAL7Z01156 and higher
KM-3040	QAQ7Z01120 and higher