

<b>SB Number:</b>	<b>SB 2H0-009</b>	<b>Creation Date: 07/07/2008</b>
<b>Subject:</b>	<b>Back ground image on print-outs</b>	
<b>Model:</b>	<b>KM-2540/3040/2560/3060</b>	

<b>Phenomenon</b>	Back ground images may appear at the machine rear side.
-------------------	---

<b>Cause</b>	The main charger is incorrectly Installed.
--------------	--

<b>Solution</b>	<p>The shape of the main charge cleaner has been changed.          The shape and thickness of the holder guide pulley has been changed.</p> <p>See page 2 for further details.</p>
-----------------	--

Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
	1	302H093011 2H093011	302H093012 2H093012	PARTS DK-670	1	1	X	O	O
	2	302H093311 2H093011	302H093312 2H093312	PARTS MC-670	1	1	X	O	O

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	Please instruct the user to insert the main charger unit firmly.			

Affected serial numbers	Type	Serial number
	KM-2540	QAL8201759 and higher
	KM-3040	QAQ8201601 and higher
	KM-2560	QAW8102245 and higher
	KM-3060	QBA8202492 and higher

## Main charger unit changes

