



<b>SB Number:</b>	<b>SB 2GR-033</b>	<b>Creation Date:</b> 01/10/2009
<b>Subject:</b>	<b>The operation panel display remains blank</b>	
<b>Model:</b>	<b>KM-3035/4035/5035/3050/4050/5050</b>	

<b>Phenomenon</b>	The operation panel display remains blank.
-------------------	--

<b>Cause</b>	<p>The wire toner disposal has been damaged, after being pinched between the inner left cover and the front frame.</p> <p>Under this condition the IC on the power supply board* becomes damaged.</p> <p>*(LVU 100 302GR45011 and LVU 200 302GR45021)</p>
--------------	---

<b>Solution</b>	The spacer wire 2BL04460 has been added, to ensure that the wire toner disposal remains in the inner left cover.
-----------------	--



Parts	No.	Affected model	Old Parts No.	New Parts No.	Description	Q'TY		Interchangeability		SP
						Old	New	Old	New	
	1	KM-3035/4035/5035	-----	2BL04460	SPACER WIRE A and B	-	2	-	O	-
	2	KM-3050/4050/5050	-----	2BL04460	SPACER WIRE A only (B already added)	-	1	-	O	-

<b>Classification</b>	<input type="checkbox"/> Entire stock rework <input type="checkbox"/> In-field modification at next visit <input checked="" type="checkbox"/> In-field modification by case <input type="checkbox"/> No modification necessary
<b>Field measure</b>	Please make sure that the wires do not get pinched during assembly or disassembly.

<b>Affected serial numbers</b>	<b>Type</b>	<b>Serial number</b>
	KM-3035/4035/5035/3050/4050/5050	June 2009 production