

<b>SB Number:</b>	<b>SB 2FZ-025</b>	<b>Creation Date: 17/04/2008</b>
<b>Subject:</b>	<b><i>Added cushioning material to prevent the Slit glass from damaging</i></b>	
<b>Model:</b>	<b>KM-C2520/3225/3232/2525E/3232E/4035E</b>	

<b>Phenomenon</b>	It may be possible that the Slit glass gets broken during transport.
-------------------	--


<b>Solution</b>	To reduce the load from boxes that are stacked on top of the machine, the cushioning material has been changed.
-----------------	---

Top surface previous condition



Folding type pad (prevents Slit glass from moving)

Top surface current condition




4 built up pads have been added to absorb possible shocks

Current condition




There is no cushion material (Position X); cushion material will be placed here.

Previous packing condition of Slit glass and Contact glass



Folding type pads

Current packing condition of Slit glass and Contact glass



Built up type pads

<b>Classification</b>	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
<b>Field measure</b>	When transporting the machine, make sure that no heavy boxes are placed on top of the machine box, especially boxes that are smaller (See Service bulletin 2H0-006 for details).			

Affected serial numbers	Type	Serial number
	KM-C4035E	Production from January 2008 and later.
	All other MFP's	Production from February 2008 and later.