

SB Number:	SB 2FZ-024	Creation Date: 07/07/2008
Subject:	Colour misalignment in main scan direction, all colours	
Model:	KM-C2525E/C3232E/C4035E	

Phenomenon	All colours are misaligned due to the settings of U467 or U020 has been performed.
-------------------	--

Solution	<ol style="list-style-type: none"> 1. If the setting in U467 are OFF change it to ON. 2. Perform user adjustment, colour calibration. 3. Perform user adjustment, colour registration. <p>Note: If U020 was performed all settings in U468, except main scan are set to 0.</p>
-----------------	---

Classification	<input type="checkbox"/> Entire stock rework	<input type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input checked="" type="checkbox"/> No modification necessary
Field measure	Please note the above mentioned procedures.			