

SB Number:	SB 2BG-011	Creation Date: 15/08/2005
Subject:	Firmware Upgrade	
Model:	KM-C2630/C2630D	

The firmware for these machines is upgraded as follows.

Contents of changes

	Item	Remarks	Version
1	Measures against the incorrect detection of C0640 (Hard disk problem)	<p>This problem occurs during T7 control in the middle of job processing. For that reason, it might not be possible to process the image to bitmap from HDD within a set time and C0640 (Hard disk problem) might occur.</p> <p>In situations where the inside temperature of the machine is over 43°C and page-coverage rate is low (providing the following conditions are met at copy output) there is a possibility that the setting time might be too great.</p> <ul style="list-style-type: none"> • Duplex • Memory copy • No rotation output • No size unification • Sort • Lustrous • 1 in 1 (No N-up setting, No booklet split setting) <p>Measures Changes have been made so that the HDD timer is not counted during T7 control.</p>	<ul style="list-style-type: none"> • SCAN • ENG
2	Simplifying the adjustment work on production lines.	---	<ul style="list-style-type: none"> • SCAN
3	Correcting the maintenance mode U118 (Displaying drum history)	<p>In the maintenance mode U118 (Displaying drum history), the following items are displayed in the current circumstances. The items are corrected according to the specification.</p> <p><i>Current status</i> The main unit number and <u>total</u> counter value are displayed.</p> <p><i>After change</i> The main unit number and <u>drum</u> counter value are displayed.</p>	<ul style="list-style-type: none"> • ENG
4	Measures against the incorrect detection of C7610 (Image density measurement timing problem)	<p>Although the sampling result is unlikely to detect the error, a service call message is counted. Therefore the following change is made.</p> <ul style="list-style-type: none"> • There was a problem in the calculation of finding patch density. Thus the correction is made so that the calculation is properly done. 	<ul style="list-style-type: none"> • ENG

Firmware specifications:

Type	Program No.	File Name	Check SUM		
SCANNER	2BG2931CP	DE12	282		← New upgrade
ENGINE	2BG2932ER	6D48	175		← New upgrade
LANGUAGE E	2BG29345F	2012	61	For Europe, Asia and Oceania spec.	

Field measure

If the problem arises, please upgrade to the latest firmware.

Affected machine serial numbers

KM-C2630/2630D: V3007705 and higher