



SB Number:	SB 2BG-020	Creation Date: 17/12/2008
Subject:	Broken edge of the guide TC F	
Model:	KM-C2630/2630D	

Phenomenon	The edge of the guide TC F 2BG02600 at the front of the machine may get cracked or brake off. Even when the edge of the guide TC F brakes off, it is unlikely it will cause a problem. However in rare cases image failure or paper jam may occur.
-------------------	---


Solution	Install plate TC guide F 302BG68580 to strengthen the edge of the guide TC F.
-----------------	---



Phenomenon; Damaged edge of the **guide TC F**



Solution; Replace guide TC F, install **plate TC guide F** and fix it with a **screw**



Parts	No.	Old Parts No.	New Parts No.	Description	Q'TY		Interchange-ability		SP
					Old	New	Old	New	
	1	-----	302BG68580 2BG68580	PLATE TC GUIDE F	-	1	-	O	-

Classification	<input type="checkbox"/> Entire stock rework	<input checked="" type="checkbox"/> In-field modification at next visit	<input type="checkbox"/> In-field modification by case	<input type="checkbox"/> No modification necessary
Field measure	When the above mentioned phenomenon occurs, please replace the guide TC F and install plate TC guide F.			

Affected serial numbers	Type	Serial number
	KM-C2630/2630D	Not available