

SB Number:	SB 2BG-005	Creation Date: 05/02/2005
Subject:	Vertical white lines on image (change 'MCH UNIT')	
Model:	KM-C2630, KM-C2630D	

Phenomenon & Cause


If over time there is not sufficient pressure anymore from the main charger wire cleaning pad, the main charger wire is unevenly wiped at cleaning. As a result, uneven discharge might occur and vertical white lines may occur on the image.

Countermeasure

The material of the cleaning pad has been changed to improve the pressure of cleaning pad.

Material change: **OLD:** Felt → **NEW:** Seagull

Reverse side of 'MCH UNIT' at rear side of machine.



Field Measure

If the phenomenon arises, please replace with part no. 1 with new part.

Parts Table

No.	Part No. OLD	Part No. NEW	Description	Q'ty		Interchangeability	
				Old	New	X	O
1	2BG68110	302BG93210 2BG93210	PARTS, MCH UNIT, SP	1	1	X	O

Affected Machine Serial Numbers:

KM-C2630/C2630D: V3004163 and later