

SB Number:	SB 2BG-009	Creation Date: 03/03/2005
Subject:	'LEVER LOCK CONTAINER' damaged (toner container)	
Model:	KM-C2630 / C2630D	

## Phenomenon

If the toner container is pulled out in the condition that the '**LEVER LOCK CONTAINER**' is not released first, the '**LEVER LOCK CONTAINER**' might become damaged.



## Countermeasure

To prevent the '**LEVER LOCK CONTAINER**' from being damaged, some reinforcing ribs and a round surface finishing have been added to the '**LEVER LOCK CONTAINER**' for ensuring its strength.

When replacing toner container, please follow the procedures below.

### Toner container replacement

1. Open toner container cover.
2. Push the bottom bar on '**LEVER LOCK CONTAINER**' until the bar makes a click sound. Only after releasing the locked condition, lift up the toner container slightly and pull out the toner container.



## Field Action

If the phenomenon should arise, please replace old part no. 1 with new part no. 1. In addition, please instruct the user to pull out the toner container only after releasing the '**LEVER LOCK CONTAINER**'.

## Parts Table

No.	Part No. OLD	Part No. NEW	Description	Q'ty		Interchange ability	
				Old	New		
1	2BG09200	302BG09201 2BG09201	LEVER LOCK CONTAINER	4	4	X	O

### Affected Machine Serial Numbers:

KM-C2630/C2630D: V3002706 and later