

<b>SB Number:</b>	<b>SB 2BG-016</b>	<b>Creation Date:</b> 03/08/2006
<b>Subject:</b>	<b>Measure against strange sounds heard from the fuser section</b>	
<b>Model:</b>	<b>FS-C8026N, KM-C2630/C2630D</b>	

## Phenomenon

Because the joints section of the gears (2BG2249\_/2BG2246\_) in the fuser drive assy can have a small gap, there is a possibility that an abnormal sound (The clicking sound) is heard at every rotation.

## Contents of change

To reduce the chance that the gears joint section produces unwanted noise, the SPACER GEAR will be supplied as a spare parts to fill up the space causing the gear knocking.

Old part number	New part number	Description	Q'ty		Interchange ability	
			Old	New	Old	New
-----	302BG68360 2BG68360	SPACER GEAR	-	1	-	○

## Affected machine serial numbers:

Not available due to the spare parts.

## Field Measure:

When an abnormal sound is heard coming from the FUSER DRIVE ASSY, please attach the SPACER GEAR.

## FUSER DRIVE SECTION

### SPACER GEAR, p/n: 302BG68360

